

Figure 1




Figure 2




Figure 3




Figure 4



Section A



Section B



Section C




Figure 5




Figure 6





Figure 7

Conventional versus ducted fan lift distribution




FIGURE 8




Figure 9





Figure 10



Section A

Section B




Figure 11

Route of flight over personnel's heads




Figure 12




Figure 13




Figure 14




Figure 15




Figure 16





Figure 18






Figure 20




Figure 21




Figure 22




Figure 23




Figure 24